

SITE INSPECTION REVIEW FORM

FILE COPY

SITE NAME: HUDSON OIL REFINERY  
ALIASES: QUANTA RESOURCES  
SITE I.D.#: NYA 980534499

<u>ITEM</u>	<u>COMPLETE ?</u>	
	<u>YES</u>	<u>NO*</u>
SITE LOCATION (INCLUDING MAP)	___	___
SITE BACKGROUND	___	___
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	___	___
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	___	___
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	___	___
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	___	___
POTENTIAL FOR DIRECT CONTACT	___	___
CONCLUSIONS + RECOMMENDATIONS	___	___
REFERENCES	___	___

HRS PRE-SCORE: PRELIMINARY SCORE = \_\_\_\_\_  
PROJECTED SCORE = \_\_\_\_\_



COMMENTS:

Site Dealt w Waste Oils

No GW or SW Targets

Some Cleanup was undertaken by NYC DEP.

NFRAT —

REVIEWED BY:

Ben Cozetta

DATE:

2/14/91

\*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS